


Ocloc™ V

+ SPINE HOLES

OCLOC V Repair System for wooden posts 100mm screw hole spacings Galfan protected.



OCLOC V 3 screws supplied.

Ocloc Broken Wood Post Solution V

Tonnes Fruit Per Hectare	CV 900mm	CV 1050mm	BV 900mm	BV 1050mm	BV 1200mm	AV 900mm	AV 1050mm	AV 1200mm
0 - 6	●	●						
6 - 12			●	●	●			
12 - 30			●	●	●	●	●	●
30 - 40						●	●	●
50								


Pricing includes 4 x 75mm batten screws and delivery within 200km from Adelaide excludes GST

Product Code	Lengths Available			Width	Metal Density	Thickness of Galfan Steel
CV	900mm	1050mm	NA	80mm	600 G	1.6mm
BV	900mm	1050mm	1200mm	80mm	450 - 500 G	1.8mm
AV	900mm	1050mm	1200mm	100mm	450 - 500 G	1.8mm





More information please scroll down. Please look at options 1,2 and 3

Ocloc™ BV

OCLOC V is a cost effective repair system for broken wooden posts.




Ocloc BV Profile



Option 1

Zig Zag


3 x 75mm screws



Option 2

Central

3 x 100mm screws



Option 3

Triangle

2 x 75mm screws
1 x 100mm screw

