

Repair Broken Wooden Posts

Designed & Manufactured in Australia

Ocloc V - Long term fix for broken wooden posts

Material: High tensile G450 steel

Coating: Galfan - aluminium, rare metals, zinc and magnesium

The ultimate in corrosive resistance and durability

Thickness: CV 1.6mm

BV 1.8mm

Lengths: Available in 900mm, 1.05m, 1.2m, 2.4m

Ocloc V fits onto the broken post with no sharp edges, ideal for under vine management

Eliminates: New toxic, costly to install replacement posts not required

- no more post to the grave yard / toxic stock piles
- eliminates cutting staples or remove plastic clips
- eliminates tractors and dangerous rear mounted rammers, no hard panning on the soil

Positives: Quick & easy: "find, repair, move forward"

- One pass not 5 movements
- Costs reduction 50%
- maintain or achieve Organic status
- reduce carbon inputs and Ocloc products are carbon offset


Equipment Required: Petrol rammer, side by side or 4-wheeler and trailer, impact driver, claw hammer

Screws: 4 shark tooth screws and driver bit included


"find, repair, move forward"




Round side




Flat side



Half round post fix on round side - NZ Full round post fix on round side - AUST



Half round post fix on flat side - NZ



Quarter round post fix on flat sides - NZ

Ocloc products are carbon neutral at manufacturing — 100% carbon offset



www.ocloc.com.au

Ocloc Sales Enquiries Nigel Catt - 0418 832 967 Administration


0488 662 562 nigel@ocloc.com.au admin@ocloc.com.au






Repair Broken Wooden Posts


Designed & Manufactured in Australia




Ocloc V profile



AUST



AUST



Screw Placement



Ocloc V - Petrol Ramming



Ocloc V - Screwing



Ocloc V video



Bugle Batten Screw, 75mm come in boxes of 500.



Ocloc CV 1.6mm thick **BV** 1.8mm thick

Available in lengths

900mm, 1.05m, 1.2m, 2.1m, 2.4m

Bundles of 252

⁶⁶Find, repair, move forward ⁹⁹

Ocloc products are carbon neutral at manufacturing — 100% carbon offset



www.ocloc.com.au

Ocloc Sales Enquiries Nigel Catt - 0418 832 967 Administration

0488 662 562 nigel@ocloc.com.au admin@ocloc.com.au





Repair Broken Wooden Posts

Designed & Manufactured in Australia



CCA Waste = time, money, frustration and adds pollution

Prevent vineyard waste and maintain your posts without removing wires or removal of broken posts. No more toxic, arsenic impregnated new timber post that could break again and reduce profitability.

Ocloc is the solution with one pass through the vineyard.



⁶⁶Find, repair, move forward ⁹⁹

Ocloc products are carbon neutral at manufacturing — 100% carbon offset



www.ocloc.com.au

Ocloc Sales Enquiries
Nigel Catt - 0418 832 967
Administration

0488 662 562 nigel@ocloc.com.au admin@ocloc.com.au

